

MECKLENBURG COUNTY CODE ENFORCEMENT

RESIDENTIAL
BUILDING CODE
INTERPRETATIONS
AND
CLARIFICATIONS

NCRC 1998-2012

COI	DE	
INT	ERPRETA	MECKLENBURG COUNTY Building Code Enforcement
	CODE:	2012 NC RESIDENTIAL CODE
	SUBJECT:	ACCESSORY BUILDING FOOTERS AND DIMENSION
	REVIEWED:	BUILDING CONSISTENCY TEAM
		sory storage building where is the 12' in any direction measured to and can an accessory ding be built on stacked blocks, how far apart can they be spaced?
	Code refere Chapter 1 se	ence: ection R101.2 scope
	in any direct mean roof li treated joists following pr      Prec     Run     Max	ment for a permit is based upon any <b>plan dimension</b> (no overhangs) greater than 12' tion; also with any vertical height that is greater than 12' (measured from grade to ne). Many buildings are elevated due to topography or ground clearances for non-s/subfloor. The department has allowed based upon previous engineering the ractice: tast solid blocks/footers or cap blocks can be used and dry stacked on grade ners must be minimum 4x4 trimum clear span between blocks is 4' at the 400 square feet or less, 1 story and tied down at the corners per section R101.2

Approved By <u>Jeff Vernon</u> Date <u>12/29/2015</u>

CODE			
INTERPRETATION	MECKLENBURG COUNTY Building Code Enforcement		
Code: 2006 NO	C RESIDENTIAL CODE		
SUBJECT: BRICK FLA	ASHING – PIER AND CURTAIN WALL FOUNDATION		
REVIEWED: RESIDENT	TIAL CONSISTENCY TEAM		
Code reference: Sections R703.7.5, R70  Answer:  No. The North Carolin 1998 in which DOI state  "flashing and w	na Department of Insurance issued a formal interpretation on January 14 <sup>th</sup> ,		

Approved By Gene Morton Date 1/1/08

CODE	
	& Cano

### MECKLENBURG COUNTY

### **INTERPRETATION**

**Building Code Enforcement** 

Code: 2006 NC Residential Code

SUBJECT: EGRESS REQUIREMENTS FOR DETACHED GARAGES (ACCESSORY BUILDINGS)

REVIEWED: RESIDENTIAL CONSISTENCY TEAM

### **Question:**

What are the requirements for egress on a single story detached garage; garages with storage above & garages with habitable space above?

### **Code reference:**

Section R311 & Chapter 2 Definition of Accessory Building


#### **Answer:**

The residential Code requires a means of egress out of an accessory building (detached) since not a dwelling unit egress can be provided in the following examples:

**Example #1**- A single story detached garage only, no fixed stairs to attic storage or no storage above can use the overhead door as a the sole means of egress from that space.

<u>Example #2</u>- A detached garage with a fixed set of stairs to storage only must have a compliant door per section R311.4 Stairs can be open to garage (no separation required).

**Example #3**- A detached garage with a fixed set of stairs to habitable space above must have a compliant door per section R311.4 not passing through a garage per R311.4.1 and separation requirements as listed in section R309. This could be accomplished by stair chase with drywall separating stairs/egress door from garage or an exterior flight of stairs off upper level.



Approved By Gene Morton Date 1/1/08

CODE			
INTERPRETATION	MECKLENBURG COUNTY Building Code Enforcement		
CODE: 2012 NC R	ESIDENTIAL CODE		
Subject: Exterior Doc	OR SWING DIRECTION		
REVIEWED: RESIDENTIAL	CONSISTENCY TEAM		
Sections R311.3, R311.3.1  Answer: Door swing differs betwee	n the required exit door and all other exterior doors.		
Note these definitions:	Landing is minimum 3' x 3'. Floor is any area greater than a landing.  Steps/Stairway is more than one contiguous riser		
Required Exit Door:	Must have landing or floor on each side of door. Floor or landing may be 1.5" lower than threshold on non-swing side.  Exception: The Exterior landing or floor shall not be greater than 8.25 inches below the top of the threshold provided the door does not swing over the landing or floor.		
Other Exterior Doors:	Floor or landing may be 8.25" lower than threshold regardless of door swing. 8.25" may only occur on one side of the door – 1.5" must occur on the other side regardless of door swing.  May have stairway (no landing) to door on exterior side provided door swings in. (Note: this same no landing rule applies to interior doors provided door does not swing over stairway)		

Approved By <u>Jeff Vernon</u> Date <u>1/28/16</u>

CODE						
INTERPRETA	TION	MEC			COUNT Enforcemen	
Code:	2006 NC R	ESIDENTIAL COD	)E			
SUBJECT:	Engineered	FOOTER/FOUND	ATION REPAIRS	(PIER SYSTEM	5)	
REVIEWED:	RESIDENTIAL	. Consistency T	ГЕАМ			
helical piers <u>Code refer</u>	ence:	pections are req			foundation repair	rs such as
Answer:  1. Fooreq per 2. Fin a en to b	oter inspection uired to be or mit document al inspection- ngineer's letter be on site for	<u>n</u> - At time of font is ite for field is s. When all work is that signs off of inspector to re	ooter inspection inspector revious is completed a on installation view and collo	on an engined ew and to col final inspect meeting desig ect. In additi	ering deign lette llect to place on ion will be condu in requirements on the grade ar is still provide	i file with ucted and will need cound the

Approved By Gene Morton Date 1/1/08

CODE		
INTERPRETA	MECKLENBURG COUNTY Building Code Enforcement	
Code:	2012 NC RESIDENTIAL CODE	
SUBJECT:	ENGINEERED HELICAL PIER FOUNDATIONS REPAIRS	
REVIEWED:	RESIDENTIAL CONSISTENCY TEAM	
	ation and inspections are required for engineered helical pier foundation repairs?	
Code reference Section R30	nce: 1.1.3 & NC Administrative Code and Policies section 105.	
	rmit must be issued before work begins and there are two inspection trips a juired as follows:	re
req das call insj des 2. <u>Fin</u> an (tyj wit	er inspection- At time of footer inspection an engineering deign letter will ired to be provided (typically uploaded to the permit from contracto board) for field inspector to review that design is sealed. Inspection should d in the day work begins however contractor doesn't have to wait. Upon arrivector will verify work in progress and that design is sealed by a NC register professional.  Linspection- When all work is completed a final inspection will be conducted a ngineer's letter that signs off on the completed installation shall be provideally uploaded to the permit). The inspector will verify that an appropriate let language that covers the scope of work has been provided and inspect to see the grade around the structure has been restored (positive drainage).	r's be val ed nd ed ter

<u>Note</u>: This process is different for commercial structures which will require special inspections per Chapter 17 of the NC Building Code.

Approved By Lon McSwain Date 08/24/2015

CODE	

### **MECKLENBURG COUNTY**

### **INTERPRETATION**

### **Building Code Enforcement**

CODE: 2012 NC RESIDENTIAL CODE

SUBJECT: JOISTS BLOCKING

REVIEWED: RESIDENTIAL CONSISTENCY TEAM

### **Question:**

What are the Code requirements for lapping and blocking of floor joists ends?

### **Code reference:**


Sections R502.6.1 and R502.7, R502.7, R502.7.1 and Fig. R502.2

### **Answer:**

Floor joists framed over a bearing support shall be "tied together" using a 3" overlap, wood or metal splices, or continuous floor sheathing.

In addition, floor joist ends shall be "prevented from rotating" by the use of lateral supports at each end. Joists are to frame into a header, band or rim joists, an adjoining stud, or be laterally supported by full-depth solid blocking installed between the ends of the joists.

Intermediate, mid-span blocking or bridging is not required until the joists size exceeds 2x12. Solid blocking is required between joists per R502.4 and Fig. R502.2 when there is a load from above (such as a bearing wall) and load is brought down to a lower girder or interior bearing walls. Blocking is needed to transfer load from above around floor joist at these interior bearing locations.



CODE	
	TOTAL

### **INTERPRETATION**

**VOLUME:** 2002 North Carolina Residential Code for One and Two-family Dwellings

**SUBJECT:** Minimum Stair Width

**REVIEWED BY:** Consistency Team

### **QUESTION:**

What is minimum required stair width?

### **CODE REFERENCE:**

Section R314.1

### **ANSWER:**

Stairways shall not be less than 36" in clear width above permitted handrail height and below permitted head room height. Minimum width "at and below" the handrail height shall not be less than 31.5" where a handrail is installed on one side and 27" where handrails are provided on both sides.

Approved By I	Date: 07/01/02
---------------	----------------

CODE	
	_

### INTERPRETATION

**VOLUME:** 2002 North Carolina Residential Code for One and Two-Family Dwellings

**SUBJECT:** Multiple Wythe Masonry Bonding

**REVIEWED BY:** Consistency Team

### **QUESTION:**

May bonding in a multiple wythe masonry wall be eliminated from the top of a wall down to the interval distance listed in Section R608 for a given bonding method?

#### **CODE REFERENCE:**

Section R608

### **ANSWER:**

No. The bonding methods described in Section R608 must be at the top of the wall, then at intervals listed down to the footing. Header bonding must occur in the top course and prefabricated bonding ties (e.g., Z ties or Durawire) must be in the upper most bonding bed joint of the wall.

Exception: On walls where the facing and backing wythe bed joints match elevations only every 16" (such as occurs with oversized brick and block walls) the upper most bond only may be achieved using a structure wall tie (not a veneer tie). This will allow bonding to occur no further down than 8" from the top of any wall, with Section R608 bonding to occur in the rest of the wall.

Approved By	_ Date: 06/23/9	98
-------------	-----------------	----

CODE	

# MECKLENBURG COUNTY ENGINEERING & BUILDING

### **INTERPRETATION**

STANDARDS DEPARTMENT

**VOLUME:** The North Carolina Administration and Enforcement Requirements Code

**SUBJECT:** New Residential Building Occupancy

**REVIEWED BY:** Consistency Team

### **QUESTION:**

What defines Occupancy?
When may Occupancy Occur?
What are the consequences of occupying too soon?

### **CODE REFERENCE:**

Sections 303, 307, and 308

### **ANSWER:**

Occupancy is to reside or dwell in and to maintain control over placement of personal items within the structure (other than those connected with the scope of work as shown on the permite.g. Installation of permanent fixtures and appliances)

Occupancy may only occur if a Certificate of Occupancy or a Temporary Certificate of Occupancy granted.

Occupancy prior to the above approvals shall be an illegal occupancy and to permit holder may be subject to the following:

- Disconnection of utility services
- Suspension of Temporary Power Privileges
- Revocation of Temporary Power Privileges
- Removal of occupants and their belongings to accommodate inspections
- Revocation of permits

Approved By	Date:	06/23/	98
-------------	-------	--------	----

CODE		(3)			
INTERPRETATION		MECKLENBURG COUNTY Building Code Enforcement			
CODE:	2006 NC R	ESIDENTIAL CODE			
SUBJECT:	New struct	URE THRESHOLD			
REVIEWED:	RESIDENTIAL	CONSISTENCY TE	AM		
what point  Code refer	should this be or rence:	use it is found that considered a new s dministrative Cod	structure rather th	n is required th nan a remodeli	nan original thought, a ng upfit.
Answer:					
When as a ne	i structure meets w residence with	the following 2 its h a new Certificate	ems it will be cor e of Occupancy:	nsidered a new	structure and permittee
		nes uninhabitable eeds 50% of the o			heating, etc) and mponents
along with		ce permit. Contrac			e required to be issued holds when permitting a

Approved By Gene Morton

CODE		
INTERPRETA	TION	MECKLENBURG COUNTY Building Code Enforcement
CODE:	2006 NC RE	SIDENTIAL CODE
SUBJECT:	PERMIT EXPI	RATIONS
REVIEWED:	Residential	CONSISTENCY TEAM
considered of Code reference	commences?	ount of work required in order for the work authorized by a permit to be and policies chapter 3 (GS 153A-358)
Answer:	strative Code a	and poneies enapter 5 (G5 155/1-550)
work must l with the pl	be verified and lans and the	lication that the work authorized by the permit has commenced. The d documented by an inspection, and such work must be in accordance requirements of the North Carolina State Building Codes. The work will be at the discretion of the Code Enforcement Official.
Example: <u>N</u> structures.	New one and t	wo family permits, including additions and accessory buildings and
<ul><li>The</li><li>The</li><li>The</li><li>The</li><li>requ</li></ul>	entire are un area must be area must be footing exca iired)	need to be completed in order for the permit to be commenced: der the building footprint must be cleared of trees grubbed (cleared of all vegetation stumps, roots, plants, etc.) graded evation must be completed with reinforcement steel installed (if g must be inspected and approved by the Code Official
		roval doesn't constitute a commenced project.  s the work must be performed in accordance with the Code
requiremen	ts and must l	be completed and or ready for the first required inspection.

Approved By \_\_\_\_<u>Gene Morton</u> \_\_\_\_\_\_ Date \_\_\_\_<u>1/1/08</u>

CODE				
INTERPRETA	ATION	MEC		RG COUNTY ode Enforcement
Code:	2012 NC R	ESIDENTIAL CODE		
SUBJECT:	Poured Fou	NDATION WALLS		
Reviewed	RESIDENTIAL	. Consistency Te	<b>EAM</b>	
Code refe NC Admir Answer: Yes, cond concrete for concrete pl to insure the R404.1.1(1)	rence: distrative Code as a crete walls design accement. Howe hat contractor is (2), (2), (3), (4)	and Policies sections  gned with reinforce without reinforcer ver, at the building	ement would requirement does not typic inspector's discrete quirements listed in	re an inspection. A poured in place cally require an inspection prior toon, this inspection may be required in Tables:
R404.2.3			1 : 11 P C	. 15
	rcement in the	footing or wall mu		ssional Engineers and/or Architect  1/5/2016

CODE	
	CARD

# MECKLENBURG COUNTY Building Code Enforcement

### **INTERPRETATION**

CODE:

2002 NC Residential Code

SUBJECT: Pull down attic stairs in garages

**Reviewed by:** Gene Morton/George Rogers/Jeff Griffin

Question: Does a pull down stairs, installed in the ceiling of an attached garage, have to meet the requirements for opening protection?

**Code reference**: R309

<u>Answer</u>: Yes, attic access doors in garage ceilings need to meet the opening protection requirement for garage separation per section R309.1. This is a change in the interpretation that was issued in 1993 by the Department of Insurance that allowed pull down stairs to be exempt. This will be enforced on any structure finalled after March 31<sup>st</sup>, 2006.

#### **Acceptable alternates:**

- 1. Extend the drywall separation on wall between house and garage all the way to roof deck, where possible, so that ceiling ½" sheetrock is not required.
- 2. Cover thin pull down door with ½" sheetrock or minimum 3/8" fire treated plywood adequately attached to garage side (Note: door must close completely and additional weight of sheetrock/plywood may require some type of lock, barrel bolt or other closure device to hold shut). Fire treated plywood must be factory stamped similar to what is used on townhouse roof decking at party walls.
- 3. Non-combustible metal door openings or pull down stairs.
- 4. Scuttle hole lids will need to be trimmed out with 2x material, not thin profile door or window trim/casing, to hold in place during a fire event. Other non-combustible attachments like barrel bolts, hinge and hasp could be used.
- 5. Cover scuttle hole lids or pull down stair doors with adequately attached 24 gage (0.48mm) sheet steel as allowed for duct penetrations listed under R309.1.1.

Approved By	Gene Morton	Date	2/24/06	
		· · · · · · · · · · · · · · · · · · ·		

CODE	
	<b>MECKLENBURG COUNTY</b>
INTERPRETATION	Building Code Enforcement

Code: 2006 NC Residential Code

SUBJECT: PULL DOWN ATTIC STAIRS AND SCUTTLE HOLES IN GARAGE CEILINGS

REVIEWED: RESIDENTIAL CONSISTENCY TEAM

### **Question:**

Does a pull down stair/scuttle hole, installed in the ceiling of an attached garage, have to meet the requirements for opening protection?

### **Code reference:**

Section R309.1 Opening protection & Section R309.2 Separation required

#### Answer:

Yes, attic access doors in garage ceilings need to meet the opening protection requirement for garage separation.

#### Acceptable alternates:

- 1. Extend the drywall separation on the wall between house and garage all the way to roof deck so that ceiling 1/2" sheetrock is not required (house and garage attics are separated)
- 2. Cover thin pull down stair door with 1/2" sheetrock or minimum 3/8" fire treated plywood adequately attached to garage side (Note: door must close completely and additional weight of sheetrock/plywood may require some type of lock, barrel bolt or other closure device to hold shut). Fire treated plywood must be factory stamped similar to what is used on townhouse roof decking at party walls. Note: some pull down stair manufacturers have stairs with a fire treated plywood door cover.
- 3. Non-combustible metal door openings or non-combustible pull down stairs
- 4. Scuttle hole lids will need to be trimmed out with 2x material, no thin profile door or window trim/casing, to hold in place during a fire event. Other non-combustible attachments like barrel bolts, hinge and hasp could be used.
- 5. Cover scuttle hole lids or pull down stairs doors with adequately attached 24 gage (0.48mm) sheet steel as allowed for duct penetrations listed under R309.1.1.

		_		
Approved By(	Gene Morton	Date	1/1/08	

CODE	

### MECKLENBURG COUNTY

### **INTERPRETATION**

**Building Code Enforcement** 

Code: 2006 NC Residential Code

SUBJECT: RAFTER TIES

REVIEWED: RESIDENTIAL CONSISTENCY TEAM

### **Question:**

When are rafter ties required?


### **Code reference:**

Section R802.3.1

### **Answer:**

Rafter ties are required any time ceiling joists don't tie to the bottom of rafters. This would include but is not limited to the following conditions: Ceiling joists not parallel, ceiling joists don't form a wall to wall tie, rafters bearing on knee walls, rafters bearing on built up plates or beams.

The code intends for the rafter tie to resist roof trust forces at the rafter bearing. Collar ties are not rafter ties and both are required. Cathedral ceilings may be framed using a designed ridge beam.



Approved I	$\mathbf{R}_{\mathbf{V}} = \mathbf{C}$	Gene Morton	Date	- 1	/1.	/(	Ŋ	<b>₹</b>
ADDIOYCUI	<i>ر</i> ۷		Daic	- 1	/ I.	/ι	ĸ	)

Code	

### **INTERPRETATION**

**VOLUME:** The North Carolina Administration and Enforcement Requirements Code

**SUBJECT:** Residential Elevators

**REVIEWED BY:** Consistency Team

### **QUESTION:**

What are the code requirements for an elevator in a single family dwelling?

### **CODE REFERENCE:**

Sections 205 and 503.2

### **ANSWER:**

The 2002 North Carolina Residential Code for One and Two-Family Dwellings makes no reference to elevator. Unlike commercial elevators, the North Carolina Department of Labor does not inspect residential elevators. However, the Department of Labor recommends that the Code Enforcement Officials verify the following conditions:

- 1. Elevator has been installed according to manufacturer specifications
- 2. Elevator meets ANSI/ASME-A17.1
- 3. Elevator meets North Carolina Safety Code, Part 5
- 4. Elevator meets current National Electrical Code requirements.

Before a Certificate of Occupancy can be issued, the permit holder must provide the Code enforcement Official a letter from the elevator installer evidencing compliance with the above conditions.

App	roved By	:	Date:	06/23/98

CODE		
INTERPRETA	TION	MECKLENBURG COUNTY Building Code Enforcement
CODE:	2006 NC RE	SIDENTIAL CODE
SUBJECT:	RESIDENTIAL	. ELEVATORS
Reviewed:	Residential	L CONSISTENCY TEAM
Question: What are th	ne Code require	ements for residential elevators in single family dwellings?
Code refer NC Admin		and policies section 105
North Card	olina Departme	Code makes no reference to elevators. Unlike commercial elevators, the ent of Labor does not inspect residential elevators. However, the mmends that Code Enforcement Officials verify the following conditions
2. Elev	ator meets AN	installed according to manufacturer specifications. NSI/ASME-A17.1, NC residential elevator safety standards part 5. rrent National Electrical Code requirements.
		Occupancy can be issued, the permit holder must provide the Codetter from the elevator installer evidencing compliance with the above

CODE	
	CISO

### MECKLENBURG COUNTY

### **INTERPRETATION**

### **Building Code Enforcement**

Code: 2012 NC Residential Code

SUBJECT: RETAINING WALL GUARDS

REVIEWED: RESIDENTIAL CONSISTENCY TEAM

### **Question:**

Are guards required on retaining walls that have more than a 30" drop off to a lower grade level?

#### **Code reference:**

Section R312.1

### Answer: Yes, if part of an egress path or along other dedicated walking surface

#### DOI interpretation:

"The 2012 NC Residential Code, Section R101.2 states; "Accessory structures are not required to meet the provisions of this code except decks, gazebos and retaining walls as required by Section R404.4."


In accordance with the above, and R404.1.3, it is my opinion that the following residential retaining walls require design and are therefore required to be permitted:

- 1. All retaining walls with an unbalanced condition exceeding 48 inches
- 2. All retaining walls that cross over property lines
- 3. All retaining walls that support buildings and their accessory structures

The NC Residential Code, Section R312.1 states; "Porches, balconies, or raised floor surfaces located more than 30 inches (762 mm) above the floor or grade below shall have guards ...... in height." The NC commentary for this section states: "The guard provisions of this code address the issue of providing protection for occupants from falling off of any elevated walking surface."

It is my opinion that guards (complying with R312) must be included on any of the above mentioned retaining walls when the finished area on the high side of the wall is more than 30 inches above the grade below and part of an egress route or other dedicated walking surface".

<u>In addition</u> if the egress route or dedicated walking surface (not grass, but could include-concrete, gravel, pavers, wood walkways, etc...) is within 36" of a retaining wall meeting the requirements as listed above, a guard will be required. To not be considered adjacent to a retaining wall there needs to be at least 36" or greater level grade separation between the retaining wall and walking surface as illustrated below and can be made up of grass area or mulch bed with plantings. A steep grade associated with the walking surface where someone stepping off and cannot regain their balance will require a guard regardless of separation distance.



CODE	
	<b>MECKLENBURG COUNTY</b>
INTERPRETATION	<b>Building Code Enforcement</b>

Code: 2006 NC Residential Code

SUBJECT: RISER HEIGHT AT THRESHOLDS

REVIEWED: RESIDENTIAL CONSISTENCY TEAM

### **Question:**

Where is the riser height measure at door openings with thresholds?

### **Code reference:**

Section R311.5.3.1

#### Answer:


The requirements are specific at exterior doors with landings based upon door swing excluding storm or screen doors. The same standards of measurement as listed below for exterior doors shall apply to interior applications that use thresholds.

### **Exterior:**

- If a door is <u>outswing</u> the landing cannot be lower than 1 ½" below <u>top of threshold</u> (flush landing, no riser-this is a landing required application based upon door swing).
- If a door is *inswing* the landing cannot be lower than 8 ¼" below **top of threshold**. Landings are not required in this application (inswing door) so stair flights must meet same last riser height limit of 8 ¼" to top of threshold if landing is not installed.

#### **Interior:**

• Section R311.5.3.1 doesn't specifically list an interior threshold when the Code states "The height of the top and bottom riser shall be measured from permanent finished surface to permanent finished surface (carpet excluded)". Thresholds not listed but the intent of the Code is to include thresholds in riser heights when installed. Such interior application would be garages; doors to unfinished basements and attics.



Approved By Gene Morton	Date	1/1/08	
-------------------------	------	--------	--

CODE	
	MI

### **INTERPRETATION**

VOLU ME:	2002 North Carolina Residential Code for One and Tw	o-Family	Dwellings

SUBJECT: Sack Concrete for Deck Supports

**REVIEWED BY:** Consistency Team

### **QUESTION:**

Can sack concrete be used for deck footings?

### **CODE REFERENCE:**

Section R402.2 and Appendix M

### **ANSWER:**

Yes. Mecklenburg County Code Officials will allow sack concrete to be used as long as manufacturer guidelines are followed, including guidelines for compressive strength. The North Carolina State Building Code specifies that a minimum compressive strength of 2,500 PSI is required for concrete footings. Manufacturer mixtures (water to concrete ratios) are outlined on the sack concrete bag for footings and other requirements.

Approved By	Date	2-10-98	
rippioved by	Date	_2 10 70	

CODE	
	CAN

**INTERPRETATION** 

CODE: 2006 NC RESIDENTIAL CODE

SUBJECT: SEALED CRAWL SPACE PERMIT

REVIEWED: RESIDENTIAL CONSISTENCY TEAM

**Question:** 

Is a permit required for sealing a crawl space on an existing home?

#### Code reference:

Section 106.1 of the NC Administrative Code and Policies ("permit required for all work described in the technical codes unless specifically exempted by the North Carolina Statutes or the technical codes")

#### **Answer:**

No building permit would be required unless the work exceeded \$5,000 in cost.

Mechanical and or electrical permits, regardless of cost, may be required based upon the design.

The NC General statutes GS153A-357 and 160A417 states no permit (building) is required if the work is in a single family dwelling (commercial has no exceptions) and the cost of the work is \$5,000 or less and is not structural in nature. No building permit would be required for installation within this scope; work over \$5,000 would require a building permit and inspections.

Work \$5,000 or under would still need to be installed correctly and would fall back upon the owner of the property.

A mechanical and or electrical permit is required for any modifications to existing mechanical or electrical systems that are made to meet one of the space moisture control methods found in section R409.5 such introduction of supply air with backflow dampers or introduction of continuous conditioned air. Any additional work such as installing an outlet for a dehumidifier or wiring in a mechanical fan would require an electrical permit.

Modifications to these systems would require a licensed contractor in that field.				
Approved ByGene Morton	Date	3/12/09		
$F: \c CORE \c CORESUP \c KATHY \c GENE \c CDEINTRP \c wythe.do \c Coresum \$	oc			

CODE	
	_

### **INTERPRETATION**

VOLUME: Volume VII

SUBJECT: Shims Under Wood Beams

REVIEWED BY: Consistency Team

QUESTION:

How do I shim under a wood beam that less than 1-1/2 inches or greater than 1

½ inches above a pier?

CODE REFERENCE: Section R-108 and R-201.1

#### ANSWER:

It is acceptable to shim wood beams less than 1-½ inches or greater than 1½ inches if the following steps are followed.

- a. The center of the beam must be in center third of the shim.
- b. The center of shim bearing must be in center third of member on which it bears.
- c. The shim must extend at least  $1-\frac{1}{2}$  inches beyond the beam on each side.
- d. The minimum width dimension of the shim must equal or exceed the length dimension of the shim.
- e. If the shims are built up in layers they must be connected to prevent movement.
- f. The shim must be of the same grade and species of material as the beam. If a lower grade and species of material is used the bearing stresses must be checked by an engineer or architect. Shims can also be of steel as long as they meet items listed in a,b,c,d,e, listed above.
- g. If built up wood shims are provided, then the wood grain of each shim must be perpendicular to the adjacent layer.

Approved By	 Date	_11-3-99

CODE				
INTERPRET	ATION	MEC	KLENBURG COUNTY Building Code Enforcement	
CODE:	2006 NC Res	SIDENTIAL CODE		
SUBJECT:	SHIMS UNDER	R WOOD BEAMS		
Reviewed	: RESIDENTIAL	CONSISTENCY TI	EAM	
Code refe NC Adm Answer: It is accep 1. Th 2. Sh su 3. Th sh 4. If 5. Sh sp Sh 6. If	ptable to shim we be center of the bear must be comport across bear are minimum width im. The shims are builtims must be of the shims can also be obtained by the adjacent layer.	eam must be in the pletely under beam width, also shint had dimension of the lilt in layers it must the same grade a is used the bearing of steel as long as times are provided, er.	-	of the grade itect.

CODE		
INTERPRE	TATION	MECKLENBURG COUNTY Building Code Enforcement
Code:	2006 NC Re	ESIDENTIAL CODE
Subject	: SITE ADDRES	SSS
Reviewe	d: Residentia	AL CONSISTENCY TEAM
can temp  Code ref	the correct way to orary address be	o post an address on a property, size, on house or can it be on the mailboe up at final, etc
Answer:		
included uniform installed placed of high. Th numbers public tr where th numeral roadway a contra	review of City ity across all Do at time of final in the house itself in the house itself it is to be bigger (if avel way for rease main driveways which are to be the number.	Code requirements issue was also discussed with Fire/Medic which yof Charlotte and Mecklenburg County local ordinance to verifice partments with interpretation. The permanent numbers must be inspection to very compliance with the Code. The numbers need to left and per County ordinance (section 19-99) they must be minimum ust be plainly visible from the road frontage, which could require if needed) to be seen from the road. If structure is too far from the easonably sized numbers to be seen, the property owner shall ere ay to the building intersects the public travel way an additional set of be legible from vehicles traveling at the prevailing speed on the others must be plainly visible which may require them to be installed and. Numbers should be installed on a fixed surface to remain always.

Approved By Gene Morton Date 1/1/08

COD	)E					
INTE	RPRETA	TION	ME	CKLENBU Building		
	Code:	2006 NC R	RESIDENTIAL CO	DDE		
	SUBJECT:	DEFINITION C	DF A SLEEPING I	Room (Bedroom)		
I	Reviewed:	RESIDENTIAL	L CONSISTENCY	ТЕАМ		
	Code refere Section R31 210-71 Smole Answer:  A sleeping redoor and on for sleeping library, etc.  Exception:	coom (bedroom to more close or more close and includes to doors (less sections).	Egress require ) required.)  om) is defined osets which approximately s rooms which (such as typical as than six feet definition above to Section R310 or an exterior rical Code required	by Mecklenburg C pears to be designed may be identified  ly found above garathigh) are not require complianted Emergency Egress I door opening directle	ounty as: An end for, or which as; den family  ges) that do not ired to comply  ce with all of the Required which y from the room	al code?  trical Code is section  nclosed room with a could likely be used room, study, office.  t have storage closets with sleeping room  ne Code requirements requires an approved in In addition, Section d and in the area just

Approved By Gene Morton Date 1/1/08

Code	
INTERPRETATION	MECKLENBURG COUNTY ENGINEERING & BUILDING STANDARDS DEPARTMENT
VOLUME:	Volume VII
SUBJECT:	Soil Tests
REVIEWED BY:	Consistency Team
QUESTION:	WHEN IS THE <u>ONE/TWO FMILY SUBGRADE VERIFICATION FORM</u> REQUIRED.
CODE REFERENCE	: SECTION 401.4 SOIL TESTS
REPORTING OF SOI IS REQUIRED FOR	TE ONE/TWO FAMILY SUBGRADE VERIFICATION FORM IS REQUIRED FOR THE L TEST RESULTS CONDUCGTED BY THIRD PARTY SOIL TESTING COMPANIES. THE FORM ANY "FILLED" BUILDING PADS AND ANY QUESTIONABLE RESIDUAL SOILS AS THE BUILDING OFFICIAL THE FORM IS REQUIRED ONLY FOR ONE AND TWO FAMILY
COMPLETELY, SIGNAPPROVED BY TH LETTERHEAD) WI	L BE TRANSFERRED TO THE TESTING COMPANIES LETTERHEAD, FILLED OUT NED BY THE SOIL TESTING COMPANY'S LICENSED ENGINEER, AND SUBMITTED TO AND E BUILDING OFFICIAL. NO ALTERATIONS TO THE FORM (OTHER THAN COMPANY LL BE PERMITTED. ANY ADDITIONAL STATEMENTS SUCH AS DISCLAIMERS OR THER DOCUMENTS OR REPORTS WILL RESULT IN REJECTION OF THE FORM BY THE L.
THIS FORM IS REQ	UIRED FOR ALL ONE/TWO FAMILY PROJECTS PERMITTED ON OR AFTER JUNE 1, 1999.

Approved By\_\_\_\_\_\_ Date\_\_\_\_4-5-99

CODE	
	T CARO

### **INTERPRETATION**

**VOLUME:** 2002 North Carolina Residential Code for One and Two-Family Dwellings

**SUBJECT:** Stair Riser Height

**REVIEWED BY:** Consistency Team

### **QUESTION:**


Is the riser height on a set of interior stairs measured from the top of the threshold or the finished floor?

### **CODE REFERENCE:**

Section R314.2

### **ANSWER:**

The riser height is measured from the top of the step to the finished floor surface (excluding carpet). The threshold is not included in the riser height measurement of interior stairs



CODE	

### **INTERPRETATION**

**VOLUME:** 2002 North Carolina Residential Code for One and Two-Family Dwellings

**SUBJECT:** Step Flashing

**REVIEWED BY:** Consistency Team

### **QUESTION:**

What is the proper method of installation for step flashing at roof to wall intersection?

#### **CODE REFRENCE:**

Section R703.8 Flashing

#### **ANSWER:**

The Brick Institute of America published a design detail in Engineering and Research Digest that states the following, "a combination of tray flashing and stepped flashing should be used in areas where brick masonry intersects an adjacent sloping surface or when it surrounds a curved or sloped wall opening. Stepped flashing may be placed in every course or every other course of brick, following the bond pattern and stepping down around the opening or sloped surface. Stepped flashing in higher courses should overlap the layer of stepped flashing below by 4" (100 mm).

Approved By Da	te: 07/01/02
----------------	--------------

CODE	
	<b>MECKLENBURG COUNTY</b>
	ENGINEERING & BUILDING

**INTERPRETATION** 

STANDARDS DEPARTMENT

**VOLUME:** 2002 North Carolina Residential Code for One and Two-Family Dwellings

**SUBJECT:** Stone in Crawl Space

**REVEIWED BY:** Consistency Team

### **QUESTION:**

May washed stone be placed in the crawl area to achieve final grade?

### **CODE REFERENCE:**

Section R409

### **ANSWER:**

No. Final grade in the crawl must be achieved with soil. After final crawl grade has been inspected and approved, (foundation inspection) then stone may be added and graded. Placing stone prior to grade inspection may result in low areas being filled with stone rather than being graded properly.

Appr	oved By	Date:	07/01	1/02
	0,000	 	0 . , 0 .	.,

CODE	
INTERPRETATION MECKLENBURG ( Building Code E	
Code: 2006 NC Residential Code	
SUBJECT: STUCCO CERTIFICATION FORM	
REVIEWED: RESIDENTIAL CONSISTENCY TEAM	
<ul> <li>Question:</li> <li>When does Mecklenburg County require a Stucco compliance statement</li> <li>Code reference:</li> <li>NC Administrative Code and Policies section 105</li> </ul>	to be submitted?
Answer:  The approved stucco compliance statement must be submitted p Certification of Occupancy on any structure covered by the Resident stucco (any type) is used as the primary wall covering on any par includes structures where only dormers, bays, gables, fireplace chases, covered. A stucco compliance statement is not required where stucco brick veneer as an aesthetic covering only.	tial Building Code when tof the structure. This , or other small areas are

Approved By \_\_\_\_Gene Morton\_\_\_\_\_\_ Date \_\_\_\_\_1/1/08\_\_\_\_\_

CC	DDE						
IN	ΓERPRETA	TION	ME	CKLEN Buildi	BURG		
	CODE:	2006 NC RE	SIDENTIAL CODE	<b>=</b>			
	SUBJECT:	SURFACE WA	ATER DRAINAGE				
	REVIEWED:	Residential	L CONSISTENCY	Теам			
		•	alks required to s	slope away fro	m the foundat	ion of resider	ntial dwellings?
	Code refere Section R40 Answer:	01.3					
	against hou water again lot lines or proper slop	ise foundation ast house. The walls (obstacting. In these	eways along wing must have posterior exception cles that are no instances, the casurrounding	ositive draina to this requir ot controllabl contractor or	ge to prevent ement is who e by the con owner must	t trapping a en physical b tractor or o	nd ponding of arriers such as wner) prevent

Date \_\_\_\_\_1/1/08\_\_\_

Approved By \_\_\_\_Gene Morton

CODE	

### INT

	<b>MECKLENBURG COUNTY</b>
ERPRETATION	ENGINEERING & BUILDING STANDARDS DEPARTMEN
VOLUME:	Volume VII
SUBJECT:	Temporary Front Doors at Final
REVIEWED BY:	Consistency Team
CODE REFERENCE	nt doors allowed to be in place for the final inspection? erior Doors and Windows.
ANSWER: Yes, as long as the	door is weather stripped and has an R-value of at least R-1.66
Approved By	Date8-5-97

CODE	
	THE CARD

### INTERPRETATION

**VOLUME:** 2002 North Carolina Residential Code for One and Two-Family Dwellings

**SUBJECT:** Tempered Glazing / Permanent Barrier

**REVIEWED BY:** Consistency Team

### **QUESTION:**

What is considered a walking surface when determining the need for tempered glass? Does this apply to exterior walking surfaces?


#### **CODE REFERENCE:**

Section R308.4, Items 5 and 6

### **ANSWER:**

A walking surface is any interior floor. A walking surface is also any exterior surface such as decks, porches, slabs, steps or sidewalks. Tempered glass would be required when any interior or exterior walking surface is within the parameters of the code section. The existence of a permanent barrier on one side of the window would not eliminate the need for tempered glass if the conditions on other side would still require tempered glass.

# PER: MCRBC, CODE SECTION R308.4 (5), REQUIRED GLAZING--IN AN INDIVIDUAL FIXED OR OPERABLE PANEL ADJACENT TO AND WITHIN THE SAME PLANE AS A DOOR WHERE THE NEAREST VERTICAL EDGE IS WITHIN A 24 INCH ARC OF THE DOOR IN A CLOSED POSITION AND WHOSE BOTTOM EDGE IS LESS THAN 60 INCHES ABOVE THE FLOOR OR WALKING SURFACE.



Approved By \_\_\_\_\_\_ Date: 01/16/99

### **CODE**

## Mecklenburg County



### **Building Code Enforcement**

CODE: 2006 NC Residential Code

SUBJECT: Tread nosing requirements

Reviewed by: 101, 139 & 147

### Questions:

1. If a flight of stairs has a uniformed tread depth of 11" is a nosing required?

2. If a nosing is provided on an 11" tread depth stair are they required to be uniformed?

Code reference: R311.5.3.3

#### **ANSWER:**

No to both questions. Exception #1 under R311.5.3.3 states that a nosing is not required

if an 11 inch tread depth is met. If in a flight of stairs there is a uniformed 11 inch depth measured at the treads leading edges then no uniformed nosing is required. In this case, as pictured below, treads could have a variety of nosing and no nosing application as found on some stone steps as long as uniformity of the tread was maintained and depth was enough to meet the requirements of exception #1. The structural support capacity of any such nosing projection must be taken into account.


**CODE** 

# Mecklenburg County



**Building Code Enforcement** 

### **INTERPRETATION**



Approved By \_\_\_Gene Morton\_\_\_\_\_ Date\_\_\_\_1/1/08\_\_\_\_\_

 $F: \core \coresup\co$ 

CODE	

Twedge bolts" and

### INTERPRETATION

**VOLUME:** 2002 North Carolina Residential Code for One and Two-Family Dwellings

**SUBJECT:** Wall Sill Plate Anchors

**REVIEWED BY:** Consistency Team

### **QUESTION:**

What are the requirements for wall sill plate anchorage?

### **CODE REFERENCE:**

Figure R403.1.6

### **ANSWER:**

Exterior wall sill plates are required to be anchored to concrete or masonry foundations with 1/2" anchor bolts spaced at six feet maximum apart with an anchor within one foot of each ends of each plate section (doors, breaks in and sill, pipes, etc). Anchor bolts must have 7" embedment in concrete and 15" embedment in masonry.

As an alternative, other types of approved anchorage systems may be used. The system must provide an equal, or better performance, as the Code specified anchor bolts. Straps anchors, such as those manufactured by Hutch and Simpson, are installed during the wall construction. The manufacturer's installation requirements must be followed.

Other types of anchor that may be used are those installed after the foundation has been completed and includes " after the sills have been placed on the foundation and are quite often used as a corrective measure when the required anchorage has been omitted or misplaced in error. As with the strap anchors these bolts must be installed distinct accordance with the manufacturer's installation requirements with the specified spacing and embedment.  You may check with the Department for a list of approved alternate anchors.
Approved By Date: 07/08/02

CODE	



### INTERPRETATION

VOLU ME:

Volume VII

SUBJECT:

Dampproofing

REVIEWED BY:

Consistency Team

Question:

When can dampproofing be eliminated?

Code Reference:

Section 405

Answer:


Perimeter foundation dampproofing can be eliminated when the backfill against the foundation wall is less than 12" in height (please refer to Figure A below). When backfill ranges in height from 12" to 32" both dampproofing and drainage are required (please refer to Figure B below).


### Figure A

- 1. Surface drainage
- 2. Crawl space drainage
- 3. Backfill less than 12" in height does not require dampproofing

### Figure B

- 1. Surface drainage
- 2. Crawl space drainage
- 3. Dampproofing and drainage required





Approved By \_\_\_ Gene Morton Date 6-23-98

1	
1	P 1
-	UE



### INTERPRETATION

VOLUME:

Volume VII

SUBJECT:

Waterproofing

REVIEWED BY:

Consistency Team


QUESTION:

When is waterproofing required on a foundation wall?

CODE REFERENCE:

Section 406.1

ANSWER: Waterproofing is required when the backfill against the foundation wall is greater than 32" in height. This situation also requires a drainage system with the following features: 1) filter membrane, 2) gravel and 3) pipe draining to daylight. Please refer to the illustration below and to Section 406.1 for installation guidance.



	18				
	1-0-0	MorTON	Date	6-23-98	3
Approved By	(NE	1 101 10	Dute		

CODE	
INTERPRETATION	MECKLENBURG COUNTY Building Code Enforcement
CODE: 2006 NC F	Residential Code
SUBJECT: WET SETTI	NG REBAR
REVIEWED: RESIDENTI	AL CONSISTENCY TEAM
Code reference: Section R402.2, Chapte  Answer:  No. Code references list and tied prior to concret the footing inspection inspection occurs is if it reviewed and non-reviewed.	such as in footers or wall dowels?  er 43 reference ACI 318, NC Administrative Code  eted require all reinforcing steel to be in place and properly supported ete placement. Administrative Code section requires completion before may occur. The only way any reinforcing steel may be placed after the et is not shown on and/or required by approved plans. This applies to ewed plans alike. Rebar shown on any plans sealed by a North Carolina all be considered as a required part of the designs.
Wet setting of foundati holder habitually fails	on anchors (straps and bolts) should not be prohibited unless a permit to properly place them.

Date \_\_\_\_\_1/1/08\_\_

Approved By Gene Morton

Code	



### **INTERPRETATION**


**VOLUME:** 2002 North Carolina Residential Code for One and Two-Family Dwellings

**SUBJECT:** Winders

**REVIEWED BY:** Consistency Team

### **QUESTION:**

How are winders measured?



### **CODE REFERENCE:**

Section R314.4

### **ANSWER:**

Winders require a minimum tread width of 4". In addition, the tread must be at least 9" wide when measured from the narrowest part of the tread to a point no more than 12" away

Approved By:	Date: 08/05/97
ADDIOVER DV.	Datc. 00/03/7/

Code	
	MECKI ENDI

### **INTERPRETATION**

**VOLUME:** 2002 North Carolina Residential Code for One and Two-Family Dwellings

**SUBJECT:** Wood Blocking – Exterior Structural Plywood Sheathing

**REVIEWED BY:** Consistency Team

### **QUESTION:**

Is wood blocking required when a 4'x 8' structural sheathing panel does not extend to the top or bottom plate of the exterior wall?

### **CODE REFERENCE:**

Table R602.3(1)

### **ANSWER:**

Yes. All structural plywood sheathing used for bracing must meet the nailing requirements outlined in Table R602.3(1). If the structural sheathing panel edges are not attached to the structural framing, wood blocking must be installed behind the edges to meet the nailing requirements.

Approved By	Date:	12/03/97
-------------	-------	----------